

STAINLESS SELF DRILLING SCREWS

319-0205 8 X 1/2 HWH SELF DRILL SCREW 410 SS
319-0207 8 X 3/4 HWH SELF DRILL SCREW 410 SS
319-0210 8 X 1 HWH SELF DRILL SCREW 410 SS
319-0212 8 X 1-1/4 HWH SELF DRILL SCREW 410 SS
319-0215 8 X 1-1/2 HWH SELF DRILL SCREW 410 SS
319-0220 8 X 2 HWH SELF DRILL SCREW 410 SS
319-0305 10 X 1/2 HWH SELF DRILL SCREW 410 SS
319-0307 10 X 3/4 HWH SELF DRILL SCR 410 SS
319-0310 10 X 1 HWH SELF DRILL SCR 410 SS
319-0312 10 X 1-1/4 HWH SELF DRILL SCR 410 SS
319-0315 10 X 1-1/2 HWH SELF DRILL SCR 410 SS
319-0320 10 X 2 HWH SELF DRILL SCR 410 SS
319-0325 10 X 2-1/2 HWH SELF DRILL SCR 410 SS
319-0330 10 X 3 HWH SELF DRILL SCR 410 SS
319-0407 12 X 3/4 HWH SELF DRILL SCR 410 SS
319-0410 12 X 1 HWH SELF DRILL SCR 410 SS
319-0412 12 X 1-1/4 HWH SELF DRILL SCR 410 SS
319-0415 12 X 1-1/2 HWH SELF DRILL SCR 410 SS
319-0420 12 X 2 HWH SELF DRILL SCR 410 SS
319-0507 14 X 3/4 HWH SELF DRILL SCREW 410 SS
319-0510 14 X 1 HWH SELF DRILL SCR 410 SS
319-0512 14 X 1-1/4 HWH SELF DRILL SCR 410 SS
319-0515 14 X 1-1/2 HWH SELF DRILL SCR 410 SS
319-0520 14 X 2 HWH SELF DRILL SCR 410 SS
319-0525 14 X 2-1/2 HWH SELF DRILL SCR 410 SS
319-0530 14 X 3 HWH SELF DRILL SCR 410 SS

