

2 POSITION SINGLE POLE/SINGLE THROW SWITCHES



34-212 SPST 2 POSITION ON-OFF
50 AMP 6-24V
2 SCREW TERMINALS



34-213 SPST 2 POSITION ON-OFF
50 AMP 6-24V
2 SCREW TERMINALS
1-1/2" LONG HANDLE




34-500 SPST 2 POSITION ON-OFF
20 AMP @ 12V
2 SCREW TERMINALS



34-571L SPST 2 POSITION ON-OFF
20 AMP @ 12V
2 SCREW TERMINALS
1-1/2" LONG HANDLE



34-513 SPST 2 POSITION ON-OFF
10 AMP @ 12V
2 18 AWG WIRE LEADS



34-581 SPST 2 POSITION ON-OFF
20 AMP @ 12V
2 BLADE TERMINALS



34-571 SPST 2 POSITION ON-OFF
20 AMP @ 12V
2 SCREW TERMINALS



34-569 SPST 2 POSITION ON-OFF
5 AMP @ 120V
2 SOLDER TERMINALS
MICRO SIZE



34-571Q SPST 2 POSITION ON-OFF
20 AMP @ 12V
2 BLADE TERMINALS



34-571C SPST 2 POSITION ON-OFF
25 AMP @ 12V
2 16 AWG WIRE LEADS
WEATHERPROOF



34-586 SPST 2 POSITION ON-OFF
20 AMP @ 12V
4 BLADE TERMINALS
LIGHTED HANDLE

2 POSITION SINGLE POLE/DOUBLE THROW SWITCHES



34-572 SPDT 2 POSITION ON-ON
20 AMP @ 12V
3 SCREW TERMINALS



34-225 SPDT 2 POSITION ON-ON
50 AMP 6-24V
3 SCREW TERMINALS



34-572Q SPDT 2 POSITION ON-ON
20 AMP @ 12V
3 BLADE TERMINALS

3 POSITION SINGLE POLE/DOUBLE THROW SWITCHES



34-218 SPDT 3 POSITION ON-OFF-ON
50 AMP 6-24V
3 SCREW TERMINALS



34-573Q SPDT 3 POSITION ON-OFF-ON
20 AMP @ 12V
3 BLADE TERMINALS



34-573 SPDT 3 POSITION ON-OFF-ON
20 AMP @ 12V
3 SCREW TERMINALS



34-573C SPDT 3 POSITION ON-OFF-ON
20 AMP @ 12V
3 16 AWG WIRE LEADS
WEATHERPROOF

2 POSITION DOUBLE POLE/SINGLE THROW SWITCHES



34-574 DPST 2 POSITION ON-OFF
20 AMP @ 12V
4 SCREW TERMINALS



34-574Q DPST 2 POSITION ON-OFF
20 AMP @ 12V
4 BLADE TERMINALS

3 POSITION DOUBLE POLE/DOUBLE THROW SWITCHES



34-577 DPDT 3 POSITION ON-OFF-ON
20 AMP @ 12V
6 SCREW TERMINALS



34-577Q DPDT 3 POSITION ON-OFF-ON
20 AMP @ 12V
6 BLADE TERMINALS



34-577C DPDT 3 POSITION ON-OFF-ON
20 AMP @ 12V
6 WIRE LEADS
WEATHERPROOF

2 POSITION DOUBLE POLE/DOUBLE THROW SWITCHES




34-576 DPDT 2 POSITION ON-ON
20 AMP @ 12V
6 SCREW TERMINALS



34-576Q DPDT 2 POSITION ON-ON
20 AMP @ 12V
6 BLADE TERMINALS



34-587Q DPDT 2 POSITION ON-ON
20 AMP @ 12V
6 BLADE TERMINALS



34-592 DPDT 2 POSITION ON-ON
20 AMP @ 12V
6 SCREW TERMINALS
REVERSING SWITCH

MOMENTARY SWITCHES

2 POSITION SINGLE POLE/SINGLE THROW MOMENTARY SWITCHES



34-570 SPST 2 POSITION
MOM ON-OFF
20 AMP @ 12V
2 SCREW TERMINALS



34-570QP SPST 2 POSITION
MOM ON-OFF
20 AMP @ 12V
2 BLADE TERMINALS



34-579 SPST 2 POSITION
ON-MOM OFF
20 AMP @ 12V
2 SCREW TERMINALS
1-1/2" LONG HANDLE

3 POSITION SINGLE POLE/DOUBLE THROW MOMENTARY SWITCHES



34-215 SPDT 3 POSITION
MOM ON-OFF-MOM ON
50 AMP 6-24V
3 SCREW TERMINALS



34-575 SPDT 3 POSITION
MOM ON-OFF-MOM ON
20 AMP @ 12V
3 SCREW TERMINALS

3 POSITION SPDT MOMENTARY SWITCHES CONT.



34-575Q SPDT 3 POSITION
MOM ON-OFF-MOM ON
20 AMP @ 12 V
3 BLADE TERMINALS




34-575C SPDT 3 POSITION
MOM ON-OFF-MOM ON
20 AMP @ 12V
3 14 AWG WIRES
WEATHERPROOF




34-220 SPDT 3 POSITION
MOM ON-OFF-MOM ON
50 AMP 6-24V
3 SCREW TERMINALS
1-1/2" LONG HANDLE

3 POSITION DOUBLE POLE/DOUBLE THROW MOMENTARY SWITCHES




34-580 DPDT 3 POSITION
MOM ON-OFF-MOM ON
20 AMP @ 12V
6 SCREW TERMINALS



34-580Q DPDT 3 POSITION
MOM ON-OFF-MOM ON
20 AMP @ 12V
6 BLADE TERMINALS




34-580LQ DPDT 3 POSITION
MOM ON-OFF-MOM ON
20 AMP @ 12V
1-1/2" LONG HANDLE



34-591 DPDT 3 POSITION
MOM ON-OFF-MOM ON
20 AMP @ 12V
4 BLADE TERMINALS
REVERSING SWITCH



34-578 DPDT 3 POSITION
MOM ON-OFF-ON
20 AMP @ 12V
6 SCREW TERMINALS



34-578Q DPDT 3 POSITION
MOM ON-OFF-ON
20 AMP @ 12V
6 BLADE TERMINALS



25-370 TOGGLE BOOT (USED W/34-570 SERIES OR 15/32-32 THREAD)
25-371 1/2 TOGGLE BOOT (SAME AS 25-370)
34-508 TOGGLE SWITCH GUARD (USE W/2 POSITION TOGGLE SWITCHES)